

prograde
retrograde
reduction box
KM1
KM2
Electromagnet
clasp brake
winch circuit diagram